Pellegrino, Carl

From: Pellegrino, Carl

Sent: Wednesday, September 15, 2021 5:39 PM

To: Jimenez, Christopher; Kodama, Doug; Banner, Ellen; Hoppe, Shawna K; Touw, Steve

Subject: RE: Electric Transmission Feeder Y50 - Release of Dielectric Fluid to Long Island Sound - Information

Submitted Under 40 CFR 112.4(a)

I don't have more info than was entered into the Action Report, but had two calls with Sector NY on the incident. I had closed the incident as a result of it being in CG jurisdiction and deploying a response team. They had also indicated that the spilled was contained within a side-to-side boom of the area where outfall discharged and that a second boom was deployed behind it as a precautionary measure.

But again, it was closed out based on being responded to by CG.

From: Jimenez, Christopher < Jimenez. Christopher@epa.gov>

Sent: Wednesday, September 15, 2021 5:21 PM

To: Kodama, Doug < Kodama. Doug@epa.gov>; Banner, Ellen < Banner. Ellen@epa.gov>; Hoppe, Shawna K

<Hoppe.Shawna@epa.gov>; Touw, Steve <Touw.Steve@epa.gov>

Cc: Pellegrino, Carl < Pellegrino. Carl@epa.gov>

Subject: RE: Electric Transmission Feeder Y50 - Release of Dielectric Fluid to Long Island Sound - Information Submitted Under 40 CFR 112.4(a)

Yes, we received 2 two NRC reports. The first 1311005 the location given is in CG jurisdiction and second report (1311048) that was given with a slightly different location is just inside EPA jurisdiction, but was stated as being called in as a follow-up to the original report. Carl took the report and coordinated with CG. Sector NY who initiated an investigation and deployed a response team. Carl may have additional details.

Christopher A. Jimenez, OSC, Deputy Regional Incident Coordinator USEPA Region 2 2890 Woodbridge Ave. Edison NJ 08837 (732) 321-4425 (fax) (732) 906-6847 (office)

From: Kodama, Doug < <u>Kodama.Doug@epa.gov</u>>
Sent: Wednesday, September 15, 2021 4:45 PM

To: Banner, Ellen < Banner. Ellen@epa.gov >; Hoppe, Shawna K < Hoppe. Shawna@epa.gov >; Touw, Steve

<Touw.Steve@epa.gov>; Jimenez, Christopher <Jimenez.Christopher@epa.gov>

Cc: Pellegrino, Carl < Pellegrino.Carl@epa.gov >

Subject: FW: Electric Transmission Feeder Y50 - Release of Dielectric Fluid to Long Island Sound - Information Submitted Under 40 CFR 112.4(a)

Were we informed of this spill in USCG jurisdiction? If not, I guess I have my work cut out to try to convince USCG and NYSDEC that we'd like to be informed of them.

60K gallons and 48K in the water...

Ellen do as you please with this 112.4 submission.

Doug Kodama, Chief Response and Prevention Branch EPA Region 2 732-906-6905, office

From: Evangelista, Pat < Evangelista.Pat@epa.gov Sent: Wednesday, September 15, 2021 4:19 PM To: Kodama, Doug Kodama.Doug@epa.gov

Subject: FW: Electric Transmission Feeder Y50 - Release of Dielectric Fluid to Long Island Sound - Information Submitted

Under 40 CFR 112.4(a)

Hi Doug,

Please let's discuss at your convenience after you've had a chance to review.

Thanks, Pat

From: Mugdan, Walter < Mugdan, Walter@epa.gov>
Sent: Wednesday, September 15, 2021 4:11 PM

To: Evangelista, Pat <<u>Evangelista.Pat@epa.gov</u>>; Prince, John <<u>Prince.John@epa.gov</u>>; Kodama, Doug <<u>Kodama.Doug@epa.gov</u>>; LaPosta, Dore <<u>LaPosta.Dore@epa.gov</u>>; Anderson, Kate <<u>Anderson.Kate@epa.gov</u>> Cc: Laureano, Javier <<u>laureano.javier@epa.gov</u>>; Arcaya, Alyssa <<u>arcaya.alyssa@epa.gov</u>>; Tedesco, Mark <<u>Tedesco.Mark@epa.gov</u>>; Mears, Mary <<u>Mears.Mary@epa.gov</u>>; Rodriguez, Elias <<u>Rodriguez.Elias@epa.gov</u>>; Williamson, Anahita <Williamson.Anahita@epa.gov>

Subject: FYI: Electric Transmission Feeder Y50 - Release of Dielectric Fluid to Long Island Sound - Information Submitted Under 40 CFR 112.4(a)

FYI, see attached report about a spill in July.

From: Klesh, Kevin J [mailto:KLESHK@coned.com]
Sent: Wednesday, September 15, 2021 4:01 PM
To: Mugdan, Walter < Mugdan. Walter@epa.gov>

Cc: Lindberg, Karl < Lindberg.Karl@epa.gov >; todd.ghiosay@dec.ny.gov; Klesh, Kevin J < KLESHK@coned.com > Subject: Electric Transmission Feeder Y50 - Release of Dielectric Fluid to Long Island Sound - Information Submitted

Under 40 CFR 112.4(a)

Dear Walter:

Please find attached information about a release of dielectric fluid from Transmission Feeder Y50, provided in accordance with 40 CFR 112.4(a).

Thank you, Kevin Kevin J. Klesh

Assistant General Counsel

Consolidated Edison Company of New York, Inc.

Phone: 212-460-3771

E-mail: kleshk@coned.com

This communication is from the Law Department of Consolidated Edison Company of New York, Inc. and may contain confidential and privileged information. If you are not the intended recipient, please contact the sender by reply e-mail and delete this communication.